




## DenCITOmeter

- Measurement of the density
- Very easy operation
- Measurement of the dot gain value, dot value
- Grey balance



- A** Grey balance/balance difference
- B** Solid density
- C** Dot gain value

The measurement and control of your printing process has never been so easy. The DenCITOMeter is the perfect device for use with the printing machine. It provides exactly those measurement functions which are needed with the printing machine, quickly and easily: density, dot gain value, dot value and balance.

## Technical data

- Zeroing to paper white
- Measurement of density values
- Measurement of dot gain values
- Measurement of the dot value
- Measurement of density and balance difference
- Setting for calibration
- Setting of absolute or relative density
- Power supply by 2 AA (LR6) batteries (not included in the scope of delivery)
- Tolerances:  $\pm 0.01$  density,  $\pm 1$  % tonal value